

SAFETY ALERT



Safety Alert No. 415
March 8, 2021

Contact: Jason Mathews
Phone: (504) 731-1496

Inadequate Preparations in Advance of Inclement Weather Results in Excessive Rig Damage and Risk to Personnel

On Oct. 28, 2020, an active drillship in the Gulf of Mexico (GOM) sustained major damage to various operational components while evacuating the rig from an area impacted by Hurricane Zeta. Although no personnel casualties were reported, the incident presented a potential threat to rig personnel due to delaying the initiation of emergency evacuation procedures by remaining on location as a result of underestimating the severity of the storm.



Figure 1: Riser in contact with the hull after the EDS



Figure 2: Ruptured Riser Joint

On Thursday, Oct. 22, 2020, drillship personnel began monitoring weather disturbances, lower surface pressures and relatively higher amounts of moisture in the Caribbean, indicating potential organized storm development. Tropical storm growth progressed in conjunction with T-Times,* reducing over the course of six days as drilling and associated storm-prep operations continued. Throughout the six days, the drillship personnel were consistently advised by forecasters that “the [rig] location is not expected to see direct, significant impacts.” As the tropical storm began developing on Oct. 22, the well

*T-Times can be defined as the projected evergreen duration beginning with the identification of a storm and ending upon impact. T-Times should be established and constantly monitored throughout the lifecycle of a storm to assist in determining when to safely depart / evacuate the area.

experienced a kick/influx of formation fluids during operations. After circulating out the kick, the rig pumped a cement squeeze on Oct. 24. As the tropical storm transitioned into a hurricane Oct. 27, a packer was installed and tested as an additional barrier to further stabilize the well. The riser was displaced with seawater, and the work string, including the running tool, was pulled out of the hole in preparation for the hurricane. As Hurricane Zeta's arrival became imminent on Oct. 28, wind gusts were much higher than anticipated (roughly 100 miles per hour). Due to the hurricane's intensity, the rig was pushed off location toward the Red Watch Circle,* as the riser approached its maximum allowable angle of deviation. Due to the drillship's increasing proximity to the Red Watch Circle boundary, the Emergency Disconnect Sequence (EDS) function was activated, unlatching the Lower Marine Riser Package (LMRP) from the blowout preventer, allowing the rig to move off location.

After the EDS was initiated, the riser contacted the hull in the moonpool (*figure 1*) due to the severe swells that formed throughout the storm, causing damage to the riser (*figure 2*). Furthermore, the LMRP endured damage to its frame, piping, and coflex after contacting the seafloor several times. A comprehensive property damage assessment was conducted by the operator and rig owner in the days following Hurricane Zeta. Inspectors determined that the tensioner, flex joint, telescopic joint, LMRP, riser joints, cabling, and other riser-related components had sustained significant damage.

Therefore, BSEE recommends that operators and contractors consider the following:

- Collectively review the Emergency Evacuation Plan (EEP), including estimated T-Times, periodically to ensure all information is accurate, up-to-date, and understood and agreed upon by the impacted workers.
- Consider enhancing procedures in the EEP for safely securing wells in anticipation of an approaching storm to include abnormal well conditions, such as ballooning or a kick/influx.
- Review bridging documents and consider the delegation of authority regarding emergency response and control to be a joint responsibility between the operator and rig owner. Initiation of this element should invoke a collaborative effort between both parties.
- Recognize and differentiate the roles and responsibilities between the Ultimate Work Authority (UWA) in the field and onshore management for determining the course of action when severe weather is approaching.
- Maintain constant communication between the shore base and offshore assets throughout the duration of adverse weather.
- Before the start of hurricane season, verify the criteria for initiating an EDS is

* Red Watch Circle can be defined as the maximum offset / inclination the riser string and its associated components are designed to withstand when latched to a subsea BOP.

accurate and consider all factors relevant to deteriorating weather conditions.

- Define phases and corresponding actions to be taken regarding emergency evacuation based on the status of forecast risk models and T-Times, such as updating Red Watch Circle parameters.
- Analyze and confirm design limitations of risers, tensioners, LMRP, and other critical well operations equipment.
- Evaluate the direction of disconnect for potential contacts to the LMRP and associated equipment with the seafloor.
- Notify BSEE when rig movements occur, clearly indicating if emergency action was implemented, as well as if any potential damage was encountered.
- Review this Safety Alert in conjunction with [Safety Alert No. 363 – Injury Occurs when Non-evacuated Personnel Enter Weather-restricted Area](#) as well as [Safety Alert No. 401 – BSEE Identifies Improvements to Hurricane Preparedness During Risk Based Inspections](#) to reinforce the proper protocols during inclement weather conditions.

--BSEE--

A **Safety Alert** is a tool used by BSEE to inform the offshore oil and gas industry of the circumstances surrounding an accident or near miss. It also contains recommendations that should help prevent the recurrence of such an incident on the Outer Continental Shelf.

Category: Weather