

Detections Summary

Client: Malibu Unites
 22741 Pacific Coast Hwy, Suite 401
 Malibu, CA 90265-5876

Work Order: 14-08-1493
 Project Name: MHS 2014-8
 Received: 08/20/14

Attn:

Page 1 of 1

Client SampleID

<u>Analyte</u>	<u>Result</u>	<u>Qualifiers</u>	<u>RL</u>	<u>Units</u>	<u>Method</u>	<u>Extraction</u>
AIR DUCT GUY (14-08-1493-1)						
Aroclor-1254	27		15	mg/kg	EPA 8082	EPA 3540C
Aroclor-1260	31		15	mg/kg	EPA 8082	EPA 3540C
Total Aroclors	58			mg/kg		
French-MHS (14-08-1493-2)						
Aroclor-1254	200		22	mg/kg	EPA 8082	EPA 3540C
401-MHS (14-08-1493-3)						
Aroclor-1254	120000		30000	mg/kg	EPA 8082	EPA 3540C
Aroclor-1260	26000		3000	mg/kg	EPA 8082	EPA 3540C
Total Aroclors	146000			mg/kg		
505-MHS (14-08-1493-4)						
Aroclor-1254	180000		18000	mg/kg	EPA 8082	EPA 3540C
Aroclor-1260	51000		18000	mg/kg	EPA 8082	EPA 3540C
Total Aroclors	231000			mg/kg		
7-MHS (14-08-1493-5)						
Aroclor-1254	190		64	mg/kg	EPA 8082	EPA 3540C
10-MHS (14-08-1493-6)						
Aroclor-1254	32		4.2	mg/kg	EPA 8082	EPA 3540C

Subcontracted analyses, if any, are not included in this summary.

* MDL is shown