



Photo 1, April 2013: This aerial photo shows sunlight reflecting off standing water on areas that the Norfolk District Corps delineated as only partial wetlands.



Photo 2, March 2013: This aerial photo shows wide spread primary indicators of hydrology above ground. Even through vegetation 2-3 feet high, standing water is evident across large portions of the site.



Photo 3, March 2010: This photo, taken in a normal rainfall year, shows the wetland conditions at the site, typical of some areas the Corps delineated as non-wetlands. PEER believes the Corps incorrectly based its delineation on an improper ditch drainage "model" rather than actual field conditions.