

Table 1

EPA, CDPH, and DTSC review of Parcel B Rad Data Evaluation

	Trench	Fill	Building Sites	Total	% of total
Total Survey Units in Parcel B	70	110	17	197	100%
Navy recommended resampling	2	18	9	29	15%
Navy recommended reanalyzing archived samples	2	1	0	3	2%
EPA, CDPH, DTSC recommend resampling	55	87	7	149	76%
Total recommended resampling	57	105	16	178	90%
No signs of falsification found in data	13	5	1	19	10%
Regulators not yet reviewed	0	0	0	0	0%
% of total recommended resampling	81%	95%	94%	90%	

The above was for Parcel B alone. Below is for entire Shipyard.

Total Survey Units in Hunters Pt Tetra Tech EC	305	514	*
Parcel B as % of total	23%	21%	*

*Parcel B has 7 former building sites, which is 21% of the total 34. The above chart shows survey units at building sites. The number of survey units at building sites for the entire site was not available.

Table 2

Summary of EPA, DTSC, CDPH review of Parcel G Radiological Data Evaluation

	Trench	Fill	Building Sites	Total	% of total
Total Survey Units in Parcel G	63	107	32	202	100%
Navy recommended resampling	20	53	25	98	49%
EPA, CDPH, DTSC recommend resampling	39	54	5	98	49%
Total recommended resampling	59	107	30	196	97%
No signs of falsification found in data	4	0	2	6	3%
% of total recommended resampling	94%	100%	94%	97%	

The above was for Parcel G alone. Below is for entire Shipyard.

Total Survey Units in Hunters Pt Tetra Tech EC	305	514	*
Parcel G as % of total	21%	21%	*

* Parcel G has 4 former building sites, which is 12% of the total 34. The above chart shows survey units at building sites.

The number of survey units at building sites for the entire site was not available.